2. E. 6.

PISTONS

There has been an alteration to design on 'L' engine pistons.

Part numbers are :-

Displaced

UE. 6749 - Piston - 4. 100 Bore - 8:1 C/R UE. 8265

ISSUE.2.

2.E.7.

DECARBONISING SET

BENTLEY S.2. SILVER CLOUD II. PHANTOM V.

The following parts can be supplied as a set for decarbonising the above cars:-

Joint Washer Drain Tap	KB.1196/R	2
Joint, Oil Filter	UE.5710	1
Joint, Distributor Drive Cover	UE.5237	1
Joint Breather Fipe	UE.6828	1
Joint Washer Drain Plug (Sump)	KB.1093	1
Joint, Distributor Pedestal to C/Case	UE.7335	1
Joint, Tappet Cover	UE.5256	1
Washer, Tappet Cover Screws	KB.1076/R	8
Gasket, Cylinder Head	UE.5693	2
Joint, Induction Manifold	UE.4394	4
Joint, Rocker Cover	UE.4324	2
Joint, Exhaust Manifold to Cylinder Head	UE.4603	8
Joint, Exhaust Manifold to Pipe	UE.1683	2
Rubber Bush Rocker Cover	UE.6967	6
Assy Washer, Oil Filter	RE.15879	1
Joint, Support Bracket to Tee Piece	UE.6238	1
Joint, Tee Fiece to Manifold	UE.6175	1
Joint, Carburetter to Tee Fiece	UE.2628	2
Joint, Thermostat Outlet	UE.4354	1
Joint, Elbow to Manifold	UE.4349	1
Sealing Strip, Timing Gear Casing	UE.5608	1

Suitable for all chassis.

Piece number is RH. 2068

⁽i) Re-issued to include exhaust manifold joint, and to add chassis types.

2.E.8.

CAMSHAFT THRUST PLATES.

BENTLEY S.2 SILVER CLOUD II AND PHANTOM 5.

The method of securing the camshaft thrust plate screws has been by tab washers. These have been replaced by plates which lock pairs of screws.

The new thrust plate can be used in place of the old if sets of lock plates are also provided.

Displaced		New		
UE.5367 KB.7106/Z	Thrust plate Washer, tab (10 off)	UE.6155		
KB. /100/Z	Plate, lock	UE.6156	(Short)	3 off
		UE.6157	(long)	2 off

2.E.9. Addendum

Hydraulic Tappets

Bentley S2, Silver Cloud II Phantom V

The following are chassis numbers of cars which are fitted with the new hydraulic tappets.

<u>'B' Series</u> Bentley S2 (Standard Steel Cars)

Chassis

B.246.BS to B.500.BS. Even numbers only.

'B' Series
Silver Cloud II (Standard Steel Cars)

Chassis

SVB.431 to SVB.501. Odd numbers only.

<u>'A' Series</u> Bentley S2 (Long Wheelbase)

Chassis

LBA.9, 17 to 26 Inclusive.

'A' Series Silver Cloud II (Long Wheelbase)

Chassis

LCA.69 to 76 Inclusive.

<u>'A' Series</u> Bentley S2 Continental

Chassis

BC.139. AR to BC.151. AR Inclusive.

2.E.9. Addendum

- 2 -

'A' Series Phantom V

Chassis

5. AT. 50, 54 to 100. Even Numbers only.

2.E.9

HYDRAULIC TAPPETS

BENTLEY S2 SILVER CLOUD SII PHANTOM 5.

Certain improvements have been made to the hydraulic tappets and these necessitate new numbers.

Any stock at present held should be returned for replacement with the latest type.

Part numbers are :-

Displaced	New.
RH.7156	RH.7221
RH.7157	RH.7222
RH.7158	RH.7223
RH.7159	RH.7224

2. E. 10 Addendum

Engine - Crankcase

Bentley S. 2., Silver Cloud II, Phantom V

The following are chassis numbers of cars which are fitted with the new crankcase.

Bentley S. 2. (Standard steel cars)

Chassis

B.223.CT, 227, 235 to 241, 245, 247, 249, 253 to 263, 267 to 275, 279, 281, 285 to 301, 305 to 327, 331 to 351, 355 to 361, 367, 371 to 389, 393, 395, 403, 409, to 423, 429, 431, 435 to 445. Odd numbers only.

B.2.CU to B.10.CU, 14 to 38, 42 to 62, 66, 68, 70, 74, 76, 78, 82 to 102, 106, 110, 114, to 124, 128 to 200, 204 to 212, 218 to 334, 338, 340, 344 to 398, 402 to 484, 488 to 558, 562 to 756. Even numbers only.

'C' Series Silver Cloud II (Standard steel cars)

Chassis

SWC.320, 474 to 480, 484, 488 to 498, 502 to 530, 534 to 564, 570, 572, 574, 578 to 608, 612 to 628, 632 to 638, 644, 648 to 656, 660 to 666, 670, 674, 678 to 690, 694, 698 to 720 726, 728, 730. Even numbers only.

SXC.1 to SXC.25, 29, 31, 35 to 51, 55 to 69, 73, 75, 79 to 91, 97 to 121, 125 to 247, 251, 253, 255, 259 to 265, 269 to 357, 361 to 415, 419 to 467, 471 to 485, 491 to 525, 529 to 567, 571 to 607, 611 to 671.

Bentley S2 (Long Wheelbase)

Chassis

LBA.21 to 26 Inclusive.

2.E.10

- 2 -

<u>'B' Series</u> Silver Cloud II (Long Wheelbase)

Chassis

LCB.29, 33 to 38, 40, 42, 43, 45, 46, 47, 50 to 53, 55 to 59, 61 to 101 Inclusive.

'B' Series Bentley S2 Continental

Chassis

BC.29.BY, 31, 32, 33, 36, 37, 38, 41 to 49, 51 to 72, 74 to 96, 98, 99, 100 Inclusive.

'B' Series Phantom V

Chassis

5.BV.19 to 5.BV.31, 35, 39 to 101. Odd numbers only. 5.BX.2, 4, 6.

2.E.10

ENGINE - CRANKCASE

BENTLEY S2, SILVER CLOUD II, PHANTOM V

To improve cam and tappet lubrication on the engine crankcase, several holes and slots have been deleted in order to raise the oil level in the camshaft trough.

Crankcases are interchangeable, part numbers are as follows: -

Displaced	New	
UE.8140	Assy - Crankcase	UE. 8324
UE.7167	+ Crankcase	UE.8282.

+ Not supplied as individual part-

.ADDENDUM

2E11

SPARKING PLUGS

Since the original issue on this subject, a new sparking plug has been approved for use on the present production S. 2 engine. It is a platinum point type, Champion RN-13P, and is now available from Crewe.

Prices are as follows:-

Retail

15/- each

Trade (in lots of 150 or part of an assorted order for 150)

9/- each

2, E, 11

SPARKING PLUGS

Arrangements have been made to supply Champion Sparking Plugs, from our Parts Department at Crewe, at usual trade terms.

In order to ensure that the correct plug is ordered, for replacement purposes, the attached sheets give details of Champion Sparking Plugs approved by Rolls-Royce and Bentley Motors for their vehicles.

Delivery of these plugs can be made immediately and the trade price for quantities of 150 and over will be 2/11d. each, nett.

Retailers are invited to avail themselves of these facilities and orders for Sparking Plugs should be marked for the attention of the Spares Department and addressed to Rolls-Royce Ltd., Pyms Lane, Crewe.

2. E. 11.

ROLLS ROYCE AND BENTLEY

SPARKING PLUG RECOMMENDATIONS

Champion Models upe		Gap Setting	
N-8	ROLLS ROYCE		
(Part Number RE. 19735)	Phantom III, Silver Dawn,		
RE. 17735)	Silver Wraith to 1955	. 025"	
	BENTLEY		
	1946-53 Mk VI	. 025"	
	1954-55 Sports Saloon	. 025"	
N-5	ROLLS ROYCE		
(Part Number RE. 20608)	1958 onwards Silver Wraith 8:1 C.R.		
RE. 20008)	and Silver Cloud 8:1 C. R.	. 025"	
	BENTLEY		
	Continental and Continental Series S	. 025"	
	1958 onwards 'S' Series 8:1 C. R.	. 025"	
RN~8	ROLLS ROYCE		
(Part Number			
UE. 2831)	1956 onwards Silver Wraith 6.6:1 C. R.		
	Silver Cloud 6.6:1 C.R.	. 025"	
which includes	1959/60 Silver Cloud Series II V8	. 025"	
an anti-erosion	1959/60 Phantom V V8	. 025"	
resistor	DEMMINY		
	BENTLEY		
	1955-57 'S' Series, except Continental	. 025"	
	1958 'S' Series 6.6:1 C. R.	. 025"	
	1959/60 S. 2 V8	. 025"	

INFORMATION SHEETS

2. E. 11.

Champion type	Models	Gap Setting	
LB-8	ROLLS ROYCE		
(Part Number	ROLLS ROTCE		
Y. 2754)	1935, 20/25, 40/50 requiring 14	4 mm plug . 025"	
	1936-37, 20/25, 25/30	. 025"	
	1938-39, 25/30	. 025"	
	BENTLEY		
	1934-39, $3\frac{1}{2}$ litre and $4\frac{1}{2}$ litre	. 020"	
/Do not Name have	ROLLS ROYCE	UE 2703 Seeing Kin	
(Part Number Y. 2787)	All models requiring 18 mm plu	ıgs . 025"	
K-11	BENTLEY		
(formerly - 17)			
	3, $4\frac{1}{2}$, $6\frac{1}{2}$ and 8 litre to 1933	. 020"	

2. E. 12.

CYLINDER LINER SEALING RINGS

BENTLEY S2, SILVER CLOUD II, PHANTOM V.

To improve the sealing of the cylinder liners, a new material has been introduced for the sealing rings.

The rings are interchangeable, part numbers are as follows:-

Displaced			New
UE. 2993	Sealing Ring,	Cylinder Liner	UE. 8581
UE. 3527	Sealing Ring,	Cylinder Liner	UE. 8582

2. E. 13.

Issue 2.

'VEE' BELTS

BENTLEY S2, SILVER CLOUD II PHANTOM V

Goodyear 'Vee' Belts will in future be introduced as an alternative to the present Ferodo Belts.

Part numbers are as follows:-

Ferodo	Goodyear
UE. 5654 - Assy, Twin 'Vee' Belts - C/Shaft, Coolant and Steering Pump	UE. 8590
UE. 5628 - Assy, Twin 'Vee' Belts - C/Shaft and Dynamo Drive	UE. 8591.

(1) Re-issued to quote full title for 'Vee' Belt-Assembly.